

## 24'-0"

A noticeable seam will occur if not properly sealed when stacking liners. RIP RW (MS) sealed when stacking liners. when stacking liners (IM) GW GW (GM) (SM) seam will occur if not properly sealed (M5) (M5) occur if not properly M1 M1M2) Will (M4) (M6) M69W) \$ 9W) [ 9W) ΦW noticeable A noticeable (VV) (EN) (EN) (MS) (IM) (IM)

A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

damaged 10	Thimlers caased from improper storage	
Customer:		
Job Name:		
Title:		
	#912 Valley Forge Fieldstone Assembled	