


Utility Wirecut Brick - 1/3 Running Bond  
Wirecut Texture Not Shown

### Typical Section



Plastic form liners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic form liners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged form liners caused from improper storage

ITEM # 305051



1035 Little Gap Highway  
Palmerton PA, 18071  
610-826-4579  
Fax: 610-826-4614

Customer: \_\_\_\_\_  
Job Name: \_\_\_\_\_  
Title: #103A Utility Wirecut 1/3 Running Bond

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 1	Drawing Number: