


Hatch Texture For Visual Reference Only. Actual Texture Will Vary

Typical Section



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 306513



AP THERMOFORMING, LLC

1035 Little Gap Highway
 Palmerton PA, 18071
 610-826-4579
 Fax: 610-826-4614

Customer:

Job Name:

Title:

112A Modular Wirecut Brick

Drawn By:

Approved By:

Scale:

Page:

None

1

Date:

Date:

Tolerance:

Drawing Number:

$\pm 3/16$