


Utility Wirecut Brick - 1/3 Running Bond
Wirecut Texture Not Shown

Typical Section



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 304862



1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614

Customer: _____
Job Name: _____
Title: #103B Utility Wirecut 1/3 Running Bond

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 1	Drawing Number: