

Actual Stone Layout to be determined by AP

Match Stone =Typical Section = $\frac{3}{4}$ " $\frac{1}{4}$ $\frac{1}{4}$.080 HIPS Formliner

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP

	1035 Little Gap Highway	Customer:					
	Palmerton PA, 18071 610-826-4579	Job Name:					
THERMOFORMING, LLC	Fax: 610-826-4614	Title: #892B 12in Quarry Stone Type 2					



ITEM # 309060						
Drawn By:	Date:					
11 ,	Date:					
Scale: None	Tolerance: $\pm 3/16$					
Page: 1	Drawing Number:					

Formliner may require backing provided by c	customer
---	----------

This material is the confidential and proprietary property of Architectural Polymers, Inc. ("AP") that you are only permitted to use under license in connection with your business dealings with AP. Unless you and AP agree otherwise in writing, AP grants you a limited license to use these documents/plans, but you may not copy, modify, distribute. or transmit or disclose this material to others without AP's written consent. Copyright 2017 Architectural Polymers, Inc.



					А	noticeable	e seam	n will o cc	ur if not	proper	ly seal	ed wh	en stac	king liner	5.	
-	ng liners.	MI							(M1)	Ml						
	ien stacki	(M2)							(M2)	(M2)						
	sealed when stacking liners	(M3)		Z					(M3)	(M3)						
"0		(M4)							(M4)	(M4)						
8-	A noticeable seam will occur if not properly	(M1)							(M1)	Ml						
	n will occ	(M2)							(M2)	(M2)						
	eable sear	(M3)		2					(M3)	(M3)						
	A notice	(M4)							(M4)	M4						


A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage



1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

Customer:	
Job Name:	
<i>J</i> =	
Title:	
	$\#902P$ 12 \sim Order way Started Target 2 Associated 1.1
	#892B 12in Quarry Stone Type 2 Assembled



ITEM # 309	060
Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: $\pm 3/16$
Page: 2	Drawing Number: