



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and ITEM # 308822 will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage Drawn By: AMM 12/23/21 Molin Concrete Products 1035 Little Gap Highway Approved By: Date: Job Name: Palmerton PA, 18071 21-1271-WWTF Mercury Re Scale: 610-826-4579 $\pm 3/16$ None Title: AP THERMOFORMING, LLC Fax: 610-826-4614 Drawing Number: #901A 8"x16" Split Block Zipper