
Typical Cove Joint Profile



AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

U	' '	<u> </u>	
Customer:			
ob Name:			

#601-S Utility 1/3rd Running Stepped Bond

Approved By: Date: Tolerance: $\pm 1/16$ None Drawing Number:

6'-03/8" \triangle

 \triangle \triangle \angle $\angle | \triangleright$ \angle $\angle | \sum$ \triangle \triangle \triangle \angle \triangle \triangle $\angle | \sum$ $\angle | \sum$ \triangle \triangle $\angle | \triangleright$ \triangle \angle \angle \angle \triangle \angle \triangle $\angle | \triangleright$ لک لک ∠√ \triangle $\angle | \sum$ \angle Δ \triangle \triangle \triangle \triangle \triangle \angle \angle \triangle \angle \triangle \angle <u>ح</u> $\angle |$ $\angle | \sum$ \triangle $\angle | \triangleright$ \triangle \angle \angle \angle \triangle \angle \angle \triangle \triangle \triangle \triangle Δ Δ $\angle | \triangleright$ $\angle | \sum$ \angle \angle $\angle | \sum$ \triangle \triangle \triangle \angle $\angle | \triangleright$ $\angle | \sum$ $\angle | \sum$ \triangle \triangle \angle \angle \triangle Δ \triangle \angle

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for

AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

or damaged formliners caused from improper storage			
	Customer:	Dr	
	TIN	Αŗ	
	Job Name:	Sca	
	Title:		
	#601-S Utility 1/3rd Running Stepped Bond Assembled	Pa	

ITEM# 305790

rawn By: Date: oproved By: Date: Tolerance:

 $\pm 1/16$ None Drawing Number:

2