


Formliner may require backing provided by customer


This material is the confidential and proprietary property of Architectural Polymers, Inc. ("AP") that you are only permitted to use under license in connection with your business dealings with AP. Unless you and AP agree otherwise in writing, AP grants you a limited license to use these documents/plans, but you may not copy, modify, distribute. or transmit or disclose this material to others without AP's written consent. Copyright 2017 Architectural Polymers, Inc.











anent distortion to these plastic formliners and Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in pe will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for da



1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

amaged formliners caused from improper storage	ITEM # 30)4585
Customer:	Drawn By:	Date:
ob Name:	Approved By:	Date:
ïtle:	Scale: None	Tolerance: $\pm 1/16$
#602-S Modular 1/2 Running Bond	Page: 1	Drawing Number:

Formliner may require backing provided by customer	his material is the confidential and proprietary property of Architectural Polymers, Inc. ("AP") that you are only permitted to use under license in connection hith your business dealings with AP. Unless you and AP agree otherwise in writing, AP grants you a limited license to use these documents/plans, but you hay not copy, modify, distribute. or transmit or disclose this material to others without AP's written consent. Copyright 2017 Architectural Polymers, Inc.
<i>n</i>	8! - 0%
ō	
Plastic formliners MUST be stored at a temperature ra	ange of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage



1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

)	Name:	

Title:

Customer:

#602-S Modular 1/2 Running Bond Assembled

uired



ITEM #	304585
Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: $\pm 1/16$
Page: 2	Drawing Number: