


## Typical Cove Joint Profile



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

damaged forminers edused from improper storage		
Customer:		
Job Name:		
Job Ivanic.		

606-S Norman Stacked Bond

 ITEM # 305798

 Drawn By:
 Date:

 Approved By:
 Date:

 Scale:
 None

 Tolerance:
 ±1/16

 Page:
 1

 Drawing Number:

6'-03/8"

 $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\angle | \triangleright$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$ 4 5  $\triangle$  $\triangle$ 2  $\triangle$  $\triangle$  $\triangle$ ∠  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\angle | \triangleright$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$ \<u>\</u> ∠ ∠  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle \triangleright$  $\triangle$ 6'-31/32"  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$ 2 5 2 5 2 \<u>\</u> ∠ 2  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle \triangleright$  $\triangle$  $\angle$ 4 25 26  $\angle$  $\triangle$ \<u>\</u> \<u>\</u> ∠ ∠  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\angle | \triangleright$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\angle I \triangleright$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\angle l \triangleright$  $\triangle$  $\triangle$  $\triangle$  $\triangle$  $\triangle$ 

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage



1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

damaged formliners caused from improper storage			
Customer:		Draw	
Iob Name:		Appr	
Job Pranie.		Scale	
Title:	606-S Norman Stacked Bond Assembled	Page	

ITEM # 305798

2

rawn By:	Date:
,	
proved By:	Date:
ale:	Tolerance: $\pm 1/16$
None	<u> </u>

Drawing Number: