

will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP THERMOFORMING, LLC

1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614

damaged forminers caused from improper storage			
	Customer:		
	Tob Name:		


#607-S Modular Herringbone

Drawn By: Date: Approved By: Date: Tolerance:  $\pm 1/16$ None

Drawing Number:

305702

ITEM#



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

•		
	Customer:	Drawn
		Appro
	Job Name:	пррю
		Scale:
	Title:	

#607-S Modular Herringbone Assembled

ITEM # 305702

Date:

Date:

Scale: None Tolerance: ±1/16

Page: Drawing Number: