


## 24'-0"



A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damage AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

damaged formilners caused from improper storage		
Customer:		
Job Name:		
77°.1		
Title:	#898A Rustic Ashlar Assembled	

ITEM# 308237 Drawn By: Approved By: Date: Scale: Tolerance:  $\pm 3/16$ None Page: Drawing Number: