


Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 306527



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614


Customer:  
 Job Name:  
 Title: #901B 8"x16" Split Block (Rake)

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 1	Drawing Number:

24'-0"

A noticeable seam will occur if not properly sealed when stacking liners.

8'-0"  
A noticeable seam will occur if not properly sealed when stacking liners.




A noticeable seam will occur if not properly sealed when stacking liners.

A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 306527



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614

Customer:  
 Job Name:  
 Title: #901B 8"x16" Split Block (Rake) Assembled

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 2	Drawing Number: