



Stones drawn for concept only Stone layout will vary



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 308966



1035 Little Gap Highway
 Palmerton PA, 18071
 610-826-4579
 Fax: 610-826-4614

Customer:
 Job Name:
 Title: #907 Coral Ashlar Stone

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 1	Drawing Number:


22'-6"

A noticeable seam will occur if not properly sealed when stacking liners.

12'-0"

A noticeable seam will occur if not properly sealed when stacking liners.


A noticeable seam will occur if not properly sealed when stacking liners.



A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 308966



1035 Little Gap Highway
 Palmerton PA, 18071
 610-826-4579
 Fax: 610-826-4614

Customer:
 Job Name:
 Title: #907 Coral Ashlar Stone Assembled

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 2	Drawing Number: