



A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

damaged formliners caused from improper storage	
Customer:	Dr
	Sca
Job Name:	Pag
Title:	
#897A Rustic Quarried Random Lengths 15" OC Liner Details	

 ITEM # 304898

 Drawn By:
 Date:

 Scale:
 None

 Page:
 2

Drawing Number: