


\*\*\*Hatch texture for visual reference only. Actual texture will vary\*\*\*


### Typical Section



.060 HIPS Formliner

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 308341



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614


Customer:  
 Job Name:  
 Title: #918 12"x24" Split Limestone Zipper

|              |                  |
|--------------|------------------|
| Drawn By:    | Date:            |
| Approved By: | Date:            |
| Scale: None  | Tolerance: ±3/16 |
| Page: 1      | Drawing Number:  |

23'-0"

A noticeable seam will occur if not properly sealed when stacking liners.

8'-0"  
A noticeable seam will occur if not properly sealed when stacking liners




A noticeable seam will occur if not properly sealed when stacking liners.

A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage


ITEM # 308341



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614

Customer:  
 Job Name:  
 Title: #918 12"x24" Split Limestone Zipper Assembled

|              |                  |
|--------------|------------------|
| Drawn By:    | Date:            |
| Approved By: | Date:            |
| Scale: None  | Tolerance: ±3/16 |
| Page: 2      | Drawing Number:  |



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 308341



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614

Customer: \_\_\_\_\_  
 Job Name: \_\_\_\_\_  
 Title: #918 12"x24" Split Limestone Zipper Assembled Outline Only

Drawn By: \_\_\_\_\_  
 Approved By: \_\_\_\_\_  
 Scale: None  
 Page: 3

Date: \_\_\_\_\_  
 Date: \_\_\_\_\_  
 Tolerance: ±3/16  
 Drawing Number: \_\_\_\_\_