



12'-0"

4'-0"



Typical section



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 306197



1035 Little Gap Highway
 Palmerton PA, 18071
 610-826-4579
 Fax: 610-826-4614

Customer:	
Job Name:	
Title:	#921 Split Slate


Drawn By:		Date:	
Approved By:		Date:	
Scale:	None	Tolerance:	±3/16
Page:	1	Drawing Number:	

24'-0"

A noticeable seam will occur if not properly sealed when stacking liners.

8'-0"

A noticeable seam will occur if not properly sealed when stacking liners.



A noticeable seam will occur if not properly sealed when stacking liners.

A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 306197



1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614

Customer:	
Job Name:	
Title:	#921 Split Slate Assembled

Drawn By:		Date:	
Approved By:		Date:	
Scale:	None	Tolerance:	±3/16
Page:	2	Drawing Number:	