


# 927 ATOMIC ASHLAR


## 12'-0"



(M) MATCH STONES

STONE LAYOUT FOR VISUAL REFERENCE ONLY.  
ACTUAL STONE LAYOUT DETERMINED BY AP

Typical section



↙ .080 HIPS Formliner

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 306475



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614


Customer:  
 Job Name:  
 Title: #927 ATOMIC ASHLAR

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 1	Drawing Number:

A noticeable seam will occur if not properly sealed when stacking liners.

A noticeable seam will occur if not properly sealed when stacking liners.


A noticeable seam will occur if not properly sealed when stacking liners.



A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 306475



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614

Customer:	
Job Name:	
Title:	#927 ATOMIC ASHLAR ASSEMBLED

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 2	Drawing Number: