


ITEM #	309817
5	Date:
Approved By:	Date:
None	Tolerance: $\pm 3/16$
Page: 1	Drawing Number:



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage



1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

Job Name:

Title:

Customer:

#329B 3/8" Rib 2" OC Horizontal Assembled

- - -			
Pattern not designed	to stack in 4 [°] direction. A noticeable	Pattern not designed to stack in 4 direction. A noticeable seam will occur it stacking the liners in 4 direction	direction
C		C	

ITEM #	309817
Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: $\pm 3/16$
Page: 2	Drawing Number: