
Brick Texture Not Shown For Clarity



11'-8%"


Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for da

AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

damaged formliners caused from improper storage	ITEM#	311677
Customer:	Drawn By:	Date:
Job Name:	Scale: None	Tolerance: $\pm 3/16$
Title:	Page: 1	Drawing Number:
#118 Desert Grain Lap and Lock		

Liner Seam Location



Liner Seam Location

will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for da AP THERMOFORMING, LLC

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage		ITEM#	311677	
	1035 Little Gap Highway Palmerton PA, 18071	Customer: Job Name:	Drawn By: Scale: None	Date: Tolerance: ±3/16
	610-826-4579	Title:	Page: 2	Drawing Number:
HERMOFORMING, LLC	Fax: 610-826-4614	#118 Desert Grain Lap and Lock Assembled		