



#893 14" Quarry Stone  
Typical Section



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage


ITEM # 309061



1035 Little Gap Highway  
Palmerton PA, 18071  
610-826-4579  
Fax: 610-826-4614

Customer:  
Job Name:  
Title: #893 14" Quarry

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 1	Drawing Number:



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

**ITEM # 309061**



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614

Customer: \_\_\_\_\_  
 Job Name: \_\_\_\_\_  
 Title: #893 14" Quarry Assembled

Drawn By: _____	Date: _____
Approved By: _____	Date: _____
Scale: <b>None</b>	Tolerance: <b>±3/16</b>
Page: <b>2</b>	Drawing Number: _____