


AP THERMOF	ORMING, LLC


1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

Job Name:
Title:
#936A 3/8" Split Limestone 4'x8'

Customer:



ITEM # 308	427
Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: $\pm 3/16$
Page: 1	Drawing Number:



A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result i will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for



1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

n permanent distortion to these plastic formliners and or damaged formliners caused from improper storage			ITEM # 308427			
	Customer:	Drawn By:		Date:		
	Job Name:	Approved By:		Date:		
	Title:	Scale:	None	Tolerance: $\pm 3/16$		
		Page:	2	Drawing Number:		