


Typical Antique Classic Joint Profile



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP THERMOFORMING, LLC

Fax: 610-826-4614	610-826-4579	Palmerton PA, 18071	1035 Little Gap Highway
514	9	8071	lghway

Title:

ob Name:

Customer:

#602-STEC Modular Edge Cap Tumbled Brick Page:		Scale:	Appr	Draw	ent distortion to these plastic formliners and distortion to the second formliners and distortio
;e: 1	+ 4 O * * * O	le: None	Approved By:	Drawn By:	ITEM#
Drawing Number:		Tolerance: $+1/16$	Date:	Date:	308589