


Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 310154




1035 Little Gap Highway
 Palmerton PA, 18071
 610-826-4579
 Fax: 610-826-4614

Customer:
 Job Name:
 Title: #337 1 1/2" V Groove 3" O/C

Drawn By:
 Scale: None
 Page: 1
 Date:
 Tolerance: ±3/16
 Drawing Number:

24'-0"

Pattern not designed to stack in 12' direction. A noticeable seam will occur if stacking the liners in 12' direction



A noticeable seam will occur if not properly sealed before pouring


A noticeable seam will occur if not properly sealed before pouring

12'-0"

Pattern not designed to stack in 12' direction. A noticeable seam will occur if stacking the liners in 12' direction

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 310154



1035 Little Gap Highway
 Palmerton PA, 18071
 610-826-4579
 Fax: 610-826-4614

Customer:	
Job Name:	
Title:	#337 1 1/2" V Groove 3" O/C

Drawn By:		Date:	
Scale:	None	Tolerance:	±3/16
Page:	2	Drawing Number:	