



Hatch for visual reference only actual stone layout determined by AP
Formliner may require backup provided by customer

Typical Section



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 308356



1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614

Customer:	Drawn By:	Date:
Job Name:	Approved By:	Date:
Title:	Scale: None	Tolerance: ±3/16
#933 LedgeStone Drystack	Page: 1	Drawing Number:

