


Typical Section



.080 HIPS Formliner

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 306382

AP THERMOFORMING, LLC

1035 Little Gap Highway
 Palmerton PA, 18071
 610-826-4579
 Fax: 610-826-4614

Customer:
 Job Name:
 Title:

Drawn By: _____ Date: _____
 Approved By: _____ Date: _____
 Scale: None Tolerance: ±3/16
 Page: 1 Drawing Number: _____

#105B Smooth Utility Brick Half Bond