


- +0" Concrete
- +1/4" Concrete
- +1/2" Concrete

Actual Pattern May Vary



Typical Section

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage


ITEM # 309226



1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614


Customer:
Job Name:
Title: #313 Salem Staggered Type A

Drawn By:
Approved By:
Scale: None
Page: 1
Date:
Tolerance: ±3/16
Drawing Number:



- +0" Concrete
- +1/4" Concrete
- +1/2" Concrete

Actual Pattern May Vary



Typical Section

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 309227



1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614

Customer:
Job Name:
Title: #313 Salem Staggered Type B

Drawn By:
Approved By:
Scale: None
Page: 2
Date:
Date:
Tolerance: ±3/16
Drawing Number:

