



#407 Broom Finish

16'-0"



Typical Section
4'-0"



Plastic form liners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic form liners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged form liners caused from improper storage

ITEM



1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614

Customer:	
Job Name:	
Title:	407 Broom Finish 16' Direction

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 1	Drawing Number: