


Seam Location for visual reference only. Actual seam location determined by AP
 Board texture not shown for clarity



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 305623



AP THERMOFORMING, LLC

1035 Little Gap Highway
 Palmerton PA, 18071
 610-826-4579
 Fax: 610-826-4614

Customer:

Job Name:

Title:

520 Weathered Fir

Drawn By:

Approved By:

Scale:

Page:

None

1

Date:

Date:

Tolerance:

Drawing Number:

±3/16