


#116 Half Running Bond Closure Smooth Brick Lap & Lock







Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

Job Name: #116 Half Running Bond Closure Smooth Brick Lap & Lock

ITEM# 309772 Drawn By: Approved By: Date: $\pm 3/16$ None Drawing Number: