

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

ITEM # 305783



1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614


Customer:
Job Name:
Title: #602-ST 001 Modular Tumbled Brick

Drawn By:
Approved By:
Scale: None
Page: 1
Date:
Tolerance: ±1/16
Drawing Number:

Approval Signature Required _____



ITEM # 305783



Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: $\pm 1/16$
Page: 2	Drawing Number: