Formliner may require backing provided by customer	This material is the confidential and proprietary property of Architectural Polymers, Inc with your business dealings with AP. Unless you and AP agree otherwise in writing, AP	. ("AP") that you are only permitted to use under license in connection grants you a limited license to use these documents/plans, but you	Approval Signature Required		
		2'-0"			
	*				
					746
					4'-(
					_
					<u> </u>
		A-A			
		4'-0"			
	1" ¹ / ₁₆ " Typ. Draft	$3''$ $R^{1/32}$	" <u>Typ</u> <u>2</u> "	<u><u>7</u>₁₆</u>	" -+
		.080 H	IPS Formliner		
Plastic formliners MUST be stored at a temperatur will warrant them both unusable and destroyed.	re range of 55° to 85° Fahrenheit. Failure to do so will result Therefore, AP Thermoforming will NOT assume any liability f	n permanent distortion to these plastic formline or damaged formliners caused from improper st	orage		310155
	1035 Little Gap Highway	Customer:			Date:
	Palmerton PA, 18071	Job Name:		None	Tolerance: $\pm 3/16$ Drawing Number:
	610-826-4579 Fax: 610-826-4614	Title: #229.1" D:h 2" OC 1	/2// DOD	1 agu. 1	

AP THERMOFORMING.	LLC
	$, \mathbf{L} \mathbf{L} \mathbf{C}$

Fax: 610-826-4614

#338 1"	Rib 3"	OC1/	/2"	DOR
115501	IUD J	OOI	4	DOR

Formliner m	nay require backing provided by customer	This material is the confidential and proprietary property of Architectural Polymers, lu with your business dealings with AP. Unless you and AP agree otherwise in writing, A may not copy, modify, distribute. or transmit or disclose this material to others witho	nc. ("AP") that you are only permitted to use under license in connection AP grants you a limited license to use these documents/plans, but you	Approval Signature Required_		
		may not copy, modify, distribute. or transmit or disclose this material to others witho	ut AP's written consent. Copyright 2017 Architectural Polymers, Inc. 24'-0"			
		Pattern not designed to stack in 12' direction. A n	noticeable seam will occur if stacking the liners in 12'	direction		
And						A ne
noticeable						noticeable
ible s						ble se
eam /						
will o						will occur
ccur i						
if not						12'-0"
prope						12'-0" if not properly
erly s						
~ vealed						sealed be
bef						befo
ore pouring						fore po
uring						pouring
		Pattern not designed to stack in 12' direction. An	noticeable seam will occur if stacking the liners in 12'	direction		
P	lastic formliners MUST be stored at a temperature vill warrant them both unusable and destroyed. T	e range of 55° to 85° Fahrenheit. Failure to do so will result Therefore, AP Thermoforming will NOT assume any liability	in permanent distortion to these plastic formlin for damaged formliners caused from improper s	ers and torage	ITEM #	310155
			Customer:		Drawn By:	Date:
		1035 Little Gap Highway Palmerton PA, 18071	Job Name:		Scale: None	Tolerance: $\pm 3/16$
		610-826-4579	71'.1		Page: 2	Drawing Number:
АРТН	ERMOFORMING LLC	Fax: 610-826-4614	Title: #338 1" Rib 3" OC 1	1/2" DOB		



 $#338 1^{\circ}$ Rib 3° OC 1/2° DOR