


Typical Cove Joint Profile



Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

AP THERMOFORMING, LLC

1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

amaged formliners caused from improper storage							

 ITEM # 305791

 Drawn By:
 Date:

 Approved By:
 Date:

 Scale:
 None

 Tolerance:
 ±1/16

 Page:
 Drawing Number:

8'-0%"

. +				0 -(<i>37</i> 6			-
	45	45		45			45	2
	45	45	45	45	45		45	
	45	45		45			46	
	45			45			46	
	45			45			46	
	45	45	45	45	45		46	
	45	46	46	45	45		46	
	45	45		45	45		46	
	45	45		45			45	
	45	46		45			46	
<u>-U78</u>	45	45	45	45	45		45	
	77	47	47	4	47	45	4	4
0	45	45	46	45	45	46	45	45
	45			45			46	
	45	45		45			45	
	45	45	46	45	45		46	
	45	45		45	45		46	
	45			45			46	
	45	45		45			45	
	45	45		45			46	
	45	46		45			46	
	46						46	
	45	45		45			46	
	45	45	45	45	45	46	45	

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage



1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

or damaged for	mliners caused from improper storage	
Customer:		Drav
		Арр
Job Name:		
Part 1		Scale
Title:	606-S Utility Stacked Bond Assembled	Page

ITEM # 305791

rawn By:

Date:

Date:

Date:

None

Tolerance: ±1/16

Ige:

Drawing Number: