



#211 Sound Absorptive Broken 1" Rib




TEXTURE NOT SHOWN FOR CLARITY

B-B
12'-0"



Texture For Visual Reference Only. Actual Texture May Vary



Texture For Visual Reference Only. Actual Texture May Vary

Plastic form liners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic form liners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged form liners caused from improper storage

ITEM # 308801



1035 Little Gap Highway
Palmerton PA, 18071
610-826-4579
Fax: 610-826-4614

Customer: _____
Job Name: _____
Title: #211 Sound Absorptive Broken 1" Rib

Drawn By:	Date:
Approved By:	Date:
Scale: None	Tolerance: ±3/16
Page: 1	Drawing Number: