




| <u>3/811</u> |
|--------------|
| <u>M4</u> |
| |
| |
| |
| M3 |

| ITEM # | 309802 |
|-----------------|-----------------------|
| Drawn By: | Date: |
| Scale: None | Tolerance: $\pm 3/16$ |
| Page: 1 | Drawing Number: |
| | |



A noticeable seam will occur if not properly sealed when stacking liners.

Customer:

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage



1035 Little Gap Highway Palmerton PA, 18071 610-826-4579 Fax: 610-826-4614

| ob Name: | |
|----------|---------------------------|
| | |
| Title: | |
| | #919 Weathered Cut Ashlar |



| ITEM # | 309802 |
|-----------------|-----------------------|
| Drawn By: | Date: |
| Scale: None | Tolerance: $\pm 3/16$ |
| Page: 2 | Drawing Number: |
| | |